

Case History LANDFILL GROUT DESIGN/CONTSTRUCTION


SPERLING HANSEN ASSOCIATES

Grout Barrier System Design Premier St. Landfill – North Vancouver

- SHA was involve in the design of a grout barrier system to prevent leachate from entering Lynn Creek.
- The toe berm at the landfill was not effective and so a series of concrete grouted boreholes were placed in order to seal the toe berm from further leachate seepage allowing the leachate to be channeled to the leachate collector.

District Contact: Jerry Stokes (604) 990-3848

Project Budget: \$24 000



SPERLING HANSEN ASSOCIATES

#8 – 1225 East Keith Road, North Vancouver, B.C. Phone (604) 986-7723 Fax (604) 986-7734 E-Mail: sperling @sperlinghansen.com

- Landfill Siting
- Landfill Closure
- Hydrogeological Investigation
- Environmental Monitoring
- Design and Operations Plans